# Smart Adapters For Cobalt X<sup>TM</sup>, Cobalt L3<sup>TM</sup>, and Pt100 sensors

## Smart adapter (Binder connector)

### Compatible with Dickson's standard Pt100 sensors

Turn your standard Pt100 sensors into Smart-Sensors™!

Connect your sensors to Cobalt X and/or Cobalt L3 data loggers using Smart adapters with a Binder<sup>(1)</sup> connector.



## Smart adapter (Omega connector)

#### Compatible with most Pt100 sensors

Turn your Pt100 sensors into Smart-Sensors!

Connect your sensors to Cobalt X and/or Cobalt L3 data loggers using Smart adapters with an Omega<sup>(2)</sup> connector.



Omega connector

## Smart-Sensor technology

#### Maximum reliability and unprecedented ease-of-use

- Smart-Sensor technology stores all calibration information directly in on-board memory, including calibration correction coefficients (a/b or a/b/c), measurement uncertainty after calibration, drift after 1 year, and sensor serial number
- Plug-and-play operation for immediate use with no configuration required
- At recalibration time, swap with a freshly calibrated, ready-to-use sensor without any data loss or down-time
- All-digital technology for maximum consistency and reliability
- Smart-Sensors benefit from an embedded analog-digital signal converter that enables direct calibration, independently of the data logger

<sup>(2)</sup> The Omega connector allows for connection with nearly any type of Pt100 sensor.



<sup>(1)</sup> The Binder connector is Dickson's standard connector.

## **Specifications**

Smart Adapters		
General		
Model	Binder connector	Omega connector
Compatibility	Cobalt X2, Cobalt X1, Cobalt L3	
Product reference	ACC.ENR.0061	ACC.ENR.0054
Metrology		
Calibration options (1)	ISO/IEC 17025 (COFRAC) accredited Certified (non-accredited) NIST-traceable Recalibration via sensor exchange	
Characteristics		
Supported sensors	Pt100 sensors (not included)	
Cable	3-wire PTFE	
Dimensions	Cable: 100 cm (with connector)	

Calibration and recalibration requires the entire measurement chain, including the Smart Adapter and the Pt100 sensor (non included).



Distributed by:

Kenelec Scientific Pty Ltd 1300 73 22 33 sales@kenelec.com.au www.kenelec.com.au

Environmental Monitoring + Compliance Experts

**Dickson North America** Addison, IL - USA

+1 (630) 543-3747 contact@dicksondata.com Montpellier - France

+33 (0)4 99 13 67 30 contact@dicksondata.fr

Dickson Asia-Pacific Petaling Jaya- Malaysia

+6037 494 0758 contact@dicksondata.my

www.dicksondata.com

© 2022 Dickson. All rights reserved. Non-contractual document. Specifications and product photos subject to change without notice.